

Station: 1+2 Shifts Or Platoon: C Shift

Locatio	n:
4930	E 81 ST
Garfie	ld Heights OH 44125

Lat/Long: N 41° 25′ 31.44″ W 81° 37′ 37.23″

F1 - Fire Zone 1

Location Type: 1 - Street address

Incident Type: 111 - Building fire

FDID: **18039** Incident #: 2022-2804

Exposure ID: 66655857 Exposure #: 0

Incident Date: **06/11/2022** Dispatch Run #: 22-0002806

Report Completed by:	Warner , Joseph M	Warner , Joseph M ID: 74 Date: 06/15/2022		
Report Reviewed by:	Not Reviewed			
Report Printed by:	Warner , Joseph M	ID: 74	Date: 6/17/2022 Time: 13:29	

Structure Type: Enc	Structure Type: Enclosed building Property Use: 419 - 1 or 2 family dwelling							
Automatic Extinguishment System Present: Detectors Present: Cause of Ignition: Cause under investigation					n			
Aid Given or Received	: Automatic	aid received	Primary ac	tion take	en: 11 - Ex	tingu	ishment by fire service per	sonnel
Additional actions:			24 - Re	cover b	ody , -			
Losses	Pre-	Incident Va	lues					
Property: \$125,00	0.00 Prope	erty: \$125 ,	,000.00	Civilian	Injuries:	0	Fire Service Injuries:	0
Contents: \$20,000	.00 Conte	ents: \$20,0	00.00	Civilian	Fatalities:	3	Fire Service Fatalities:	0
Total: \$145,00	0.00 Total	\$145,	,000.00	Total Ca	asualties:	3	Total Fire Service Casualties:	0
Total # of apparatus	on call:		4	Total # o	of personnel	on ca	ill:	10

Special Studies	
COVID 19 was a factor in this incident.	No, COVID 19 was not a factor.

Neighboring Agencies Agency Name: Broadview Heights Fire Department **Agency ID:** 18-017 Agency Type: Fire Agency Name: Cuyahoga Heights Fire Department Agency ID: 18-031 Agency Type: Fire Agency Name: Maple Heights Fire Department **Agency ID:** 18-055 Agency Type: Fire Agency Name: Newburgh Hts **Agency ID:** 18-065 Agency Type: Fire Agency Name: Valley View Fire Department **Agency ID:** 18-093 Agency Type: Fire

2022/06/11 18:39:28 - CALLER REPORTING A HOUSE EXPLODED AND THERE ARE PARTIES INSIDE

2022/06/11 18:41:57 - PAGE SENT

2022/06/11 18:44:25 - VOICEMAIL LEFT FOR CHIEF STROPE

2022/06/11 18:47:29 - 2 HOUSES INVOLVED ONE FULLY ENGULFED

2022/06/11 18:49:46 - MUTUAL AID ENGINE FROM MAPLE HTS MUTUAL AID AIR TRUCK FROM VALLEY VIEW AND MUTUAL AID SQUAD FROM CUYAHOGA HTS.

2022/06/11 18:50:43 - UTILITIES COMPANIES HAVE BEEN CONTACTED.

2022/06/11 18:56:25 - #005 BWC IS NOT WORKING

2022/06/11 18:58:34 - CEI AND GAS COMPANIES HAVE BEEN CONTACTED. THE ETA FOR THE GAS COMPANY IS LESS THAN 60 MINUTES , THE ETA FOR CEI IS 90 MINUTES BUT THEY PUT IN A REMOTE DISCONNECT AT 1850.

2022/06/11 18:59:14 - PER GARFIELD COMMAND THERE ARE POSSIBLY TWO VICTIMS INSIDE

2022/06/11 18:59:46 - CLEVELAND WATER WAS NOTIFIED

2022/06/11 19:01:51 - SECOND VOICEMAIL LEFT FOR CHIEF STROPE

2022/06/11 19:02:03 - COMMAND ADVISING THE NEED TO RECALL 4 FIREFIGHTERS. PAGE SENT AND PHONE CALLS

INITIATED. SEE CFS 2221620070.

2022/06/11 19:09:49 - BOTH EXPOSURES ARE CLEAR PER COMMAND.

2022/06/11 19:12:18 - SECOND SQUAD REQUESTED FOR MUTUAL AID SQUAD, MUTUAL AID SQUAD REQUESTED FROM NEWBURG HTS FD

2022/06/11 19:26:46 - GAS COMPANY ON SCENE

2022/06/11 19:29:22 - DISPATCHER MIKE WITH THE STATE OF OHIO FIRE MARSHALS OFFICE WAS NOTIFIED. INCIDENT # 3131

2022/06/11 19:29:37 - FIRST ENERGY IS ON SCENE

2022/06/11 19:51:13 - MUTUAL AID ENGINE REQUSTED FROM BROADVIEW HTS FD

2022/06/11 20:14:27 - BROADVIEW HTS ENGINE IS ON SCENE

2022/06/11 20:50:32 - FD DISPATCHED AT 18:39. ENGINE 2 SQ 2 ENROUTE AT 1840, E1 ENROUTE AT E 1840. ENGINE 1 ON SCENE AT 1844 (ENGINE 1 IS COMMAND). E2 SQ 2 ON SCENE AT 1845

2022/06/11 21:39:07 - PER FD ON SCENE THE TECHINCIAL TEAM IS COMING DOWN REED AVE.

2022/06/11 21:49:35 - MAPLE ENGINE 2 IS IN SERVICE AND RETURNING TO THEIR FREOUENCY.

2022/06/11 22:38:14 - COUSIN OF THE RESIDENTS AT 4912 E 81ST ST STATED HER COUSINS ARE GETTING RING NOTIFICATIONS FROM RING THAT THE POLICE ARE AT THIER DOOR. PER THE COUSIN ALL PARTIES FROM THAT HOUSE ARE OK AND WITH HER IN WASHINGTON DC

2022/06/11 23:30:51 - GHE1 IS BACK OUT ON E 81 ST.

2022/06/11 23:33:41 - S20 AND 036 ARE ENROUTE BACK TO E 81ST ST

2022/06/11 23:47:15 - MEDICAL EXAMINERS OFFICE IS ON SCENE.

2022/06/12 00:35:45 - GHE2 WAS REMOVED FROM THE CALL IN ERROR AND TIMES WERE MODIFIED. (THE CALL WILL REFLECT THREE ROWS OF THE SAME TIMES FOR GHE2)

GHS2 ALSO WAS MODIFIED AND WILL SHOW THREE ROWS REFLECTING THE SAME TIMES FOR GHS2

GHE1 TIMES WERE MODIFIED AND WILL SHOW TWO ROWS REFLECTING THE SAME TIMES.

GHS3 TIMES WERE ADDED AND MODIFIED TO REFLECT GHE1 TIMES.

2022/06/12 00:37:57 - PER GHFD COMMAND CLEVELAND WATER WAS NOTIFIED TO SHUT THE WATER OFF AT THIS LOCATION.

2022/06/12 01:20:06 - GHE1 AND GHS3 ARE IN SERVICE AND WILL BE RUNNING OUT OF FIRE STATION 2.

2022/06/12 01:24:40 - GHE1 AND GHS3 ARE IN QUARTERS AT GHFD STATION 2.

2022/06/12 01:47:47 - TOM WITH THE RED CROSS (216-372-9913) WILL BE EN ROUTE WITH SNACKS AND BEVERAGES FOR APPROXIMATELY 50 MEMBERS STILL ON SCENE ETA 90 MINUTES.

2022/06/12 02:22:59 - CONTACT WAS MADE WITH BROADVIEW HTS FIRE DISPATCH REFERENCE THEIR LIGHT TOWER, THEY ADVISED BROADVIEW HTS FIRE PERSONNEL WILL PICK THE LIGHT TOWER UP IN THE MORNING.

2022/06/12 02:44:35 - ALL COMPANIES ARE IN SERVICE AND COMMAND HAS BEEN TERMINATED.

2022/06/12 02:49:39 - PER GHC1 RED CROSS WAS NOTIFIED TO CANCEL.

2022/06/12 03:13:20 - PER GHFD LT COST, THE STATE FIRE MARSHALL WILL BE ON SCENE IN THE MORNING TO INVESTIGATE FURTHER.

2022/06/12 04:14:04 - SEE REPORT.

2022/06/12 04:14:06 - (LD)

NARRATIVE (2)

Narrative Title: Lt. Cost Narrative Author: Cost , David Narrative Date: 06/12/2022 04:28:03 Narrative Apparatus ID: E1

Narrative:

Engine 1, Engine 2 and Squad 2 responded to 4930 East 81 St. for a report of a house that exploded with multiple calls. Dispatch was advised to put out a box alarm. Engine 1 arrived on scene with a house that was leveled and fully involved. There was an exposure on the B side that had the siding and the eves burning and an exposure on the D side that the siding was melting on. A vehicle in the driveway was fully involved. Engine 1 established Command and initiated a defensive attack. A portable monitor was placed in front of the structure and a 1 3/4" line was stretched to protect the exposure on the B side. Engine 2 arrived on scene and set up their deck gun and assisted obtaining a water supply. Maple Heights engine was advised to lay a supply line in to Engine 2 and to protect the exposure on the D side. When talking to a family member it was determined that there were three people still inside the structure. Valley View arrived on scene and was advised to check the area for debris. Dispatch was advised to notify the utilities, Chief Strope and Captain Warner. Dispatch was advised to contact a squad from the second box. Both exposures were extinguished and checked on the interior for extension. Dispatch was advised to notify the Chief of possible fatalities. Newburgh Heights squad arrived on scene and attended to a family member having Chest Pain. Main fire was controlled and attempts were made to search for victims. Chief Strope arrived on scene. State Fire Marshalls office was notified and will respond. Dispatch was advised to contact an Engine from the second box for manpower. Chief Strope contacted Eastside Tech Rescue for response. Service department was notified for a backhoe. Dominion Gas arrived on scene and had trouble shutting down the gas. First Energy arrived on scene and removed the down power lines and cut the power. Captain Warner arrived on scene. Eastside Tech Rescue arrived on scene. Debris removal was initiated to start the search. Coroners office was advised and will respond. Two victims, one male and one female were found in the C/D corner of the basement under an overturned refrigerator. Debris removal continued and a third victim, one male was found near the center of the basement. Dominion Gas will leave personnel at the scene to protect the meter. Police will patrol the area heavily over night. All Companies were returned to service and Command terminated.

APPARATUS			
	F1	11	F2
Unit	E1	Unit	E2
Type:	Ground fire suppression, other	Type:	Ground fire suppression, other
Use:	Suppression	Use:	Suppression
Response Mode:	Lights and Sirens	Response Mode:	Lights and Sirens
# of People	5	# of People	2
Alarm	06 /11/2022 18:39:16	Alarm	06 /11/2022 18:39:16
Dispatched	06 /11/2022 18:39:33	Dispatched	06 /11/2022 18:39:34
Enroute	06 /11/2022 18:40:25	Enroute	06 /11/2022 18:42:01
Arrived	06 /11/2022 18:44:33	Arrived	06 /11/2022 18:45:32
Cancelled	/ / : :	Cancelled	/ / : :
Cleared Scene	06 /12/2022 01:20:06	Cleared Scene	06 /11/2022 22:43:44
In Quarters	06 /12/2022 01:24:40	In Quarters	/ / : :
In Service	06 /12/2022 01:20:06	In Service	06 /11/2022 22:43:44
Unit	SQ 2	Unit	C2 21
Туре:	ALS unit	Туре:	Chief officer car
Use:	EMS	Use:	Other
Response Mode:	Lights and Sirens	Response Mode:	Lights and Sirens
# of People	2	# of People	1
Alarm	06 /11/2022 18:39:16	Alarm	06 /11/2022 18:39:16
Dispatched	06 /11/2022 18:39:37	Dispatched	06 /11/2022 19:43:10
Enroute	06 /11/2022 18:40:28	Enroute	06 /11/2022 19:43:12
Arrived	06 /11/2022 18:45:35	Arrived	06 /11/2022 20:17:22
Cancelled	/ / : :	Cancelled	/ / : :
Cleared Scene	06 /12/2022 01:23:18	Cleared Scene	06 /12/2022 01:20:06
In Quarters	/ / : :	In Quarters	/ / : :
In Service	06 /12/2022 02:44:15	In Service	06 /12/2022 01:20:06
Number Of People	not on apparatus: 0		

VEHICLES	
VEHICLES	
Vehicle	
Make	Chevrolet
Туре	
Model	
Color	blue
Vin Number	
Year	
License Plate Number	JHP 2614
Owner	
Name	
Phone Number	
Address	
Driver	
Name	
Phone Number	
Address	
License Number	
Driver Is Owner	No
Driver Is Resident	Undetermined
Insurance	
Company Name	
Company Policy Number	
Company Coverage Level	
Agent Name	
Agent Phone Number	
Involvement	
Law Enforcement Officer	
Police Report Or File Number	
Number Of Occupants	
Number Of Injured Occupants	
Number Of Fatalities	
Disposable Equipment Used	
Narrative Text	

FIRE			
Acres Burned	None or Less Than One	Acres Burn From Wildland Form	False
Area Of Fire Origin	Undetermined	Heat Source	Undetermined
Item First Ignited	Undetermined	Fire Is Confined To Object Of Origin	
Type Of Material	Undetermined	Cause Of Ignition	Cause under investigation
Factor Contributing To Ignition	Undetermined		-
Human Factors Contributing	None		

STRUCTURE FIRE			
Structure Type	Enclosed building	Building Status	In normal use
# Of Stories At Above Grade	1	# Of Stories Below Grade	1
Square Feet	1200	Length	
Width		Floor Of Origin	1
Fire Spread	Beyond building of or	igin	
Minor Damage	0	Significant Damage	0
Heavy Damage	0	Extreme Damage	0

ARSON		

Gender	Name	Age	Date Of Birth	Race	Ethnicity Hispanic
Male	Donald Malinowski	64	//	White	
Affiliation		Date Of In	jury	Time	Of Injury
		06 /11/2022		18 :39:	
Severity		Cause Of I	njury		
Death					
Human Fac	ctors				
Contribution	ng Factors 1	Contributi	ng Factors 2	Contr	ibuting Factors 3
Contributii	ng Factors 1	Contributi	ng Factors 2	Contr	ibuting Factors 3
Remarks					
Body was re	covered and County Coror	ers office took n	nossession		

Gender	Name	Age	Date Of Birth	Race	Ethnicity Hispanic
Male	Gerald Bateman	57	//	White	
Affiliation		Date Of I	njury	Time	Of Injury
		06 /11/202	2	18 :38	
Severity		Cause Of	Injury		
Death					
Human Fac	tors				
Contributin	g Factors 1	Contribut	ing Factors 2	Contr	ibuting Factors 3
Remarks					
Remarks					
- 1		.			
Body was rec	overed and County Coron	ers office took	possession.		
CIVILIAN C	CASUALTIES 3			Race	Fthnicity Hisnania
CIVILIAN C	CASUALTIES 3 Name	Age	Date Of Birth	Race White	Ethnicity Hispanic
CIVILIAN C	CASUALTIES 3	Age 37	Date Of Birth	White	
CIVILIAN C Gender Female	CASUALTIES 3 Name	Age 37 Date Of I	Date Of Birth // njury	White	Of Injury
CIVILIAN C Gender Female Affiliation	CASUALTIES 3 Name	Age 37 Date Of I 06 /11/202	Date Of Birth // njury 2	White Time	Of Injury
CIVILIAN C Gender Female	CASUALTIES 3 Name	Age 37 Date Of I	Date Of Birth // njury 2	White Time	Of Injury
CIVILIAN C Gender Female Affiliation Severity	Name Cassandra Bateman	Age 37 Date Of I 06 /11/202	Date Of Birth // njury 2	White Time	Of Injury
Gender Female Affiliation Severity Death Human Fac	Name Cassandra Bateman	Age 37 Date Of I 06 /11/202 Cause Of	Date Of Birth // njury 2 Injury	White Time 18:38	Of Injury :
Gender Female Affiliation Severity Death	Name Cassandra Bateman	Age 37 Date Of I 06 /11/202 Cause Of	Date Of Birth // njury 2	White Time 18:38	Of Injury
Gender Female Affiliation Severity Death Human Fac	Name Cassandra Bateman	Age 37 Date Of I 06 /11/202 Cause Of	Date Of Birth // njury 2 Injury	White Time 18:38	Of Injury :
CIVILIAN C Gender Female Affiliation Severity Death Human Fact Contributin Remarks	Name Cassandra Bateman	Age 37 Date Of I 06 /11/202 Cause Of	Date Of Birth // njury 2 Injury ting Factors 2	White Time 18:38	Of Injury :

PEOPLE PERSON 1			
Is Owner	False	Business Name	BATEMAN
Telephone Number	2164328452	Involvement	
Name	Cassandra M Bateman	Date of Birth	
Address	6018 ANDOVER BLVD APT 104 10	4 GARFIELD HTS, OH 44125-	

PEOPLE PERSON 2			
Is Owner	False	Business Name	BATEMAN
Name	CIERRA E BATEMAN	Date of Birth	
Address	4756 E 86TH ST GARFIELD HTS	5, OH 44125-	

PEOPLE PERSON 3			
Is Owner	False	Business Name	JOHNSON
Name	APRIL M JOHNSON	Date of Birth	
Address	4924 E 81ST ST GARFIELD HT	TS, OH 44125-	

PEOPLE PERSON 4			
Is Owner	False	Business Name	JOHNSON
Telephone Number	2162803818	Involvement	
Name	RIANA M JOHNSON	Date of Birth	
Address	4924 E 81ST ST GARFIELD HTS, OH 44125-		

CUSTOM FIELDS FORM	
Is this an accidentally created CAD entry? If it is, then please use incident Code 900 and actions will be action taken other	no
Did a fire Apparatus go as a first responder?	No
Did a fire apparatus go as an assist? Meaning did the engine or ladder go because the call came in as something requiring manpower	no
Was a fire apparatus called to assist for heavy patient or difficult extrication from the home?	no
Did you distribute a smoke detector?	
Did you distribute a battery or batteries?	

PERSONNEL ON CALL				
Name	Personnel Rank	Role(s)	Apparatus	
Aldridge, Nicholas	Firefighter 3rd class		SQ 2	
Cost , David A	Lieutenant		E1	
Havel, Jonathan E	Firefighter 1st class		E1	
Kappel , Bryan	Lieutenant		E2	
Large, Ronald A.	Firefighter 1st class		E1	
McConville , Michael A	Firefighter 1st class		E2	
McNeilly, Shane	Firefighter 1st class		SQ 2	
Stepka , Melissa L	Firefighter 1st class		E1	
Straka , Kevin	Firefighter 1st class		E1	
Warner , Joseph M	Executive Captain / Training		C2 21	



Station: 1+2
Shifts Or Platoon: Administration

Location:
4930 East 81 ST
Garfield Heights OH 44125

Lat/Long: N 41° 25′ 31.68″ W 81° 37′ 45.12″

F1 - Fire Zone 1 Location Type: 1 - Street address

Incident Type: 131 - Passenger vehicle fire

FDID: **18039** Incident #: 2022-2804 Exposure ID: 66742508

Exposure #: 3

Incident Date: 06/11/2022 Dispatch Run #: 22-0002806

Report Completed by:	Warner , Joseph M	ID: 74	Date: 06/17/2022
Report Reviewed by:	Not Reviewed		
Report Printed by:	Warner , Joseph M	ID: 74	Date: 6/17/2022 Time: 13:34

Structure Ty	Structure Type: Property Use: 419 - 1 or 2 family dwelling									
Automatic E	Extingu	iishment Sys	stem Present	: 🗆 De	etectors Pre	esent: 🗆	Cause of	Ignitio	n:	
Aid Given o	r Rece	ived: Autor	natic aid re	eceived	Primary a	ction take	en: 11 - E	xting	uishment by fire service per	sonnel
Additional a	Additional actions: 12 - Salvage & overhaul , 81 - Incident command									
Losses			Pre-Incide	ent Valu	ues					
Property:	\$20,	00.00	Property:	\$20,0	00.00	Civilian I	njuries:	0	Fire Service Injuries:	0
Contents:	\$600	0.00	Contents:	\$600.	00	Civilian F	atalities:	0	Fire Service Fatalities:	0
Total:	\$20,	600.00	Total:	\$20,6	00.00	Total Cas	ualties:	0	Total Fire Service Casualties:	0
Total # of a	Total # of apparatus on call: 4 Total # of personnel on call: 10			10						

Special Studies	
COVID 19 was a factor in this incident.	No, COVID 19 was not a factor.

Neighboring Agencies
Agency Name: Broadview Heights Fire Department
Agency ID: 18-017
Agency Type: Fire
Agency Name: Cuyahoga Heights Fire Department
Agency ID: 18-031
Agency Type: Fire
Agency Name: Maple Heights Fire Department
Agency ID: 18-055
Agency Type: Fire
Agency Name: Newburgh Hts
Agency ID: 18-065
Agency Type: Fire
Agency Name: Valley View Fire Department
Agency ID: 18-093
Agency Type: Fire

NARRATIVE (1)

Narrative Title: n/a

Narrative Author: Warner , Joseph Narrative Date: 06/16/2022 12:09:09 Narrative Apparatus ID: n/a

Crews arrived on scene and began protecting exposures and knocking down main body of fire. The car fire was extinguished at the same time. Car was subsequently moved after East Side Technical rescue team arrived and moved it farther away from the house so that debris removal could begin. The vehicle remains secured at the site.

11	F1	1114	F2
Unit	E1	Unit	E2
Туре:	Ground fire suppression, other	Туре:	Ground fire suppression, other
Use:	Suppression	Use:	Suppression
Response Mode:	Lights and Sirens	Response Mode:	Lights and Sirens
# of People	5	# of People	2
Alarm	06 /11/2022 18:39:16	Alarm	06 /11/2022 18:39:16
Dispatched	06 /11/2022 18:39:33	Dispatched	06 /11/2022 18:39:34
Enroute	06 /11/2022 18:40:25	Enroute	06 /11/2022 18:42:01
Arrived	06 /11/2022 18:44:33	Arrived	06 /11/2022 18:45:32
Cancelled	/ / : :	Cancelled	/ / : :
Cleared Scene	06 /12/2022 01:20:06	Cleared Scene	06 /11/2022 22:43:44
In Quarters	06 /12/2022 01:24:40	In Quarters	/ / : :
In Service	06 /12/2022 01:20:06	In Service	06 /11/2022 22:43:44
Unit	SQ 2	Unit	C2 21
Туре:	ALS unit	Туре:	Chief officer car
Use:	EMS	Use:	Other
Response Mode:	Lights and Sirens	Response Mode:	Lights and Sirens
# of People	2	# of People	1
Alarm	06 /11/2022 18:39:16	Alarm	06 /11/2022 18:39:16
Dispatched	06 /11/2022 18:39:37	Dispatched	06 /11/2022 19:43:10
Enroute	06 /11/2022 18:40:28	Enroute	06 /11/2022 19:43:12
Arrived	06 /11/2022 18:45:35	Arrived	06 /11/2022 20:17:22
Cancelled	/ / : :	Cancelled	/ / : :
Cleared Scene	06 /12/2022 01:23:18	Cleared Scene	06 /12/2022 01:20:06
In Quarters	/ / : :	In Quarters	/ / : :
In Service	06 /12/2022 02:44:15	In Service	06 /12/2022 01:20:06
Number Of People	not on annaratus: 0		

VEHICLES	
Vehicle 1G1PC5SB5F7281061	
Make	Chevolet
Туре	
Model	Cruze
Color	Blue
Vin Number	1G1PC5SB5F7281061
Year	2015
License Plate Number	JHP 2614
Owner	
Name	Cassandra Bateman
Phone Number	
Address	
Driver	
Name	Cassandra Bateman
Phone Number	
Address	
License Number	
Driver Is Owner	Yes
Driver Is Resident	
Insurance	
Company Name	Progressive Group
Company Policy Number	946488539002
Company Coverage Level	
Agent Name	Octavio Rodriquez
Agent Phone Number	681-313-4345
Involvement	
Law Enforcement Officer	
Police Report Or File Number	
Number Of Occupants	
Number Of Injured Occupants	
Number Of Fatalities	
Disposable Equipment Used	
Narrative Text	

fire debris to be examined by investigators.

FIRE			
Acres Burned	None or Less Than One	Acres Burn From Wildland Form	False
Area Of Fire Origin	Exterior, exposed surface	Heat Source	Radiated heat from another fire
Item First Ignited	Multiple items first ignited	Fire Is Confined To Object Of Origin	
Type Of Material	Plastic	Cause Of Ignition	
Factor Contributing To Ignition	Exposure fire		
Mobile Property Involve And Type	Not involved in ignition, but burned	Mobile Property Type	Automobile, passenger car, ambulance, race car
Mobile Property Make	Chevrolet	Mobile Property Year	2015
Mobile Property Model	Cruze	License Plate	JHP 2614
State	OH	VIN	1G1PC5SB5F7281061

CUSTOM FIELDS FORM	
Is this an accidentally created CAD entry? If it is, then please use incident Code 900 and actions will be action taken other	no
Did a fire Apparatus go as a first responder?	No
Did a fire apparatus go as an assist? Meaning did the engine or ladder go because the call came in as something requiring manpower	no
Was a fire apparatus called to assist for heavy patient or difficult extrication from the home?	no
Did you distribute a smoke detector?	
Did you distribute a battery or batteries?	

PERSONNEL ON CALL			
Name	Personnel Rank	Role(s)	Apparatus
Aldridge, Nicholas	Firefighter 3rd class		SQ 2
Cost , David A	Lieutenant		E1
Havel, Jonathan E	Firefighter 1st class		E1
Kappel , Bryan	Lieutenant		E2
Large, Ronald A.	Firefighter 1st class		E1
McConville , Michael A	Firefighter 1st class		E2
McNeilly, Shane	Firefighter 1st class		SQ 2
Stepka , Melissa L	Firefighter 1st class		E1
Straka , Kevin	Firefighter 1st class		E1
Warner , Joseph M	Executive Captain / Training		C2 21



Station: 1+2
Shifts Or Platoon: Administration

Location:
4924 East 81 ST
Garfield Heights OH 44125

Lat/Long: N 41° 25′ 32.4″ W 81° 37′ 45.42″

F1 - Fire Zone 1 Location Type: 1 - Street address

Incident Type: 111 - Building fire

FDID: **18039** Incident #: 2022-2804 Exposure ID: 66736488

Exposure #: 2 Incident Date: **06/11/2022** Dispatch Run #: 22-0002806

Report Completed by:	Warner , Joseph M	ID: 74	Date: 06/15/2022
Report Reviewed by:	Not Reviewed		
Report Printed by:	Warner , Joseph M	ID: 74	Date: 6/17/2022 Time: 13:33

Structure Ty	pe: Enclosed bu	uilding	Property	Use: 419 - 1	or 2 fan	nily dwelli	ng		
Automatic E	Automatic Extinguishment System Present: Detectors Present: Cause of Ignition:								
Aid Given o	r Received: N	None	Primary a	ction taken:	11 - E	xtinguish	nent	by fire service personnel	
Additional a	ictions:	12 - 9	Salvage	& overhaul,	81 - Inci	dent comn	nand		
Losses		Pre-In	ncident V	alues (
Property:	\$20,000.00	Propert	ty: \$12	25,000.00	Civilian	Injuries:	0	Fire Service Injuries:	0
Contents:	\$2,500.00	Conten	ts: \$20	,000.00	Civilian I	Fatalities:	0	Fire Service Fatalities:	0
Total:	\$22,500.00	Total:	\$14	5,000.00	Total Ca	sualties:	0	Total Fire Service Casualties:	0
Total # of apparatus on call: 4 Total # of personnel on call: 10									

Special Studies	
COVID 19 was a factor in this incident.	No, COVID 19 was not a factor.

Neighboring Agencies Agency Name: Broadview Heights Fire Department **Agency ID:** 18-017 Agency Type: Fire Agency Name: Cuyahoga Heights Fire Department Agency ID: 18-031 Agency Type: Fire Agency Name: Maple Heights Fire Department **Agency ID:** 18-055 Agency Type: Fire Agency Name: Newburgh Hts **Agency ID:** 18-065 Agency Type: Fire Agency Name: Valley View Fire Department **Agency ID:** 18-093 Agency Type: Fire

NARRATIVE (1)

Narrative Title: n/a

Narrative Author: Warner , Joseph Narrative Date: 06/15/2022 13:54:18 Narrative Apparatus ID: n/a

crews arrived on scene started putting water on both exposures and main body. House was checked for extension and none found. Occupant was able to stay the night, but then needed assistance with temporary housing.

Unit	E1	Unit	E2
Туре:	Ground fire suppression, other	Туре:	Ground fire suppression, other
Use:	Suppression	Use:	Suppression
Response Mode:	Lights and Sirens	Response Mode:	Lights and Sirens
# of People	5	# of People	2
Alarm	06 /11/2022 18:39:16	Alarm	06 /11/2022 18:39:16
Dispatched	06 /11/2022 18:39:33	Dispatched	06 /11/2022 18:39:34
Enroute	06 /11/2022 18:40:25	Enroute	06 /11/2022 18:42:01
Arrived	06 /11/2022 18:44:33	Arrived	06 /11/2022 18:45:32
Cancelled	/ / : :	Cancelled	/ / : :
Cleared Scene	06 /12/2022 01:20:06	Cleared Scene	06 /11/2022 22:43:44
In Quarters	06 /12/2022 01:24:40	In Quarters	/ / : :
In Service	06 /12/2022 01:20:06	In Service	06 /11/2022 22:43:44
Unit	SQ 2	Unit	C2 21
Туре:	ALS unit	Туре:	Chief officer car
Use:	EMS	Use:	Other
Response Mode:	Lights and Sirens	Response Mode:	Lights and Sirens
# of People	2	# of People	1
Alarm	06 /11/2022 18:39:16	Alarm	06 /11/2022 18:39:16
Dispatched	06 /11/2022 18:39:37	Dispatched	06 /11/2022 19:43:10
Enroute	06 /11/2022 18:40:28	Enroute	06 /11/2022 19:43:12
Arrived	06 /11/2022 18:45:35	Arrived	06 /11/2022 20:17:22
Cancelled	/ / : :	Cancelled	/ / : :
Cleared Scene	06 /12/2022 01:23:18	Cleared Scene	06 /12/2022 01:20:06
In Quarters	/ / : :	In Quarters	/ / : :
In Service	06 /12/2022 02:44:15	In Service	06 /12/2022 01:20:06

FIRE			
Acres Burned	None or Less Than One	Acres Burn From Wildland Form	False
Area Of Fire Origin	Wall surface: exterior	Heat Source	Heat from direct flame, convection currents
Item First Ignited	Exterior sidewall covering, surface, finish	Fire Is Confined To Object Of Origin	
Type Of Material	Plastic	Cause Of Ignition	
Factor Contributing To Ignition	Exposure fire	-	

STRUCTURE FIRE			
Structure Type	Enclosed building	Building Status	In normal use
# Of Stories At Above Grade	1	# Of Stories Below Grade	0
Square Feet	1058	Length	
Width		Floor Of Origin	1
Fire Spread	Confined to floor of origin		
Minor Damage	1	Significant Damage	0
Heavy Damage	0	Extreme Damage	0
Item Contributing Most To Spread	Exterior sidewall covering, surface, finish	Type Of Material Contributing Most To Spread	Plastic

Is this an accidentally created CAD entry? If it is, then please use incident Code 900 and actions will be action taken other	no
Did a fire Apparatus go as a first responder?	No
Did a fire apparatus go as an assist? Meaning did the engine or ladder go because the call came in as something requiring manpower	no
Was a fire apparatus called to assist for heavy patient or difficult extrication from the home?	no
Did you distribute a smoke detector?	
Did you distribute a battery or batteries?	

PERSONNEL ON CALL			
Name	Personnel Rank	Role(s)	Apparatus
Aldridge, Nicholas	Firefighter 3rd class		SQ 2
Cost , David A	Lieutenant		E1
Havel, Jonathan E	Firefighter 1st class		E1
Kappel , Bryan	Lieutenant		E2
Large, Ronald A.	Firefighter 1st class		E1
McConville , Michael A	Firefighter 1st class		E2
McNeilly, Shane	Firefighter 1st class		SQ 2
Stepka , Melissa L	Firefighter 1st class		E1
Straka , Kevin	Firefighter 1st class		E1
Warner , Joseph M	Executive Captain / Training		C2 21



Station: 1+2 Shifts Or Platoon: A Shift

Location:
4932 East 81 ST
Garfield Heights OH 44125

Lat/Long: N 41° 25′ 31.23″ W 81° 37′ 44.83″

F1 - Fire Zone 1

Location Type: 1 - Street address

Incident Type: 111 - Building fire

FDID: **18039** Incident #: 2022-2804 Exposure ID: 66735993

Exposure #: 1 Incident Date: 06/11/2022 Dispatch Run #: 22-0002806

Report Completed by:	Warner , Joseph M	ID: 74	Date: 06/15/2022	
Report Reviewed by:	Not Reviewed			
Report Printed by:	Warner Joseph M	ID: 74	Date: 6/17/2022 Time: 13:32	

Structure T	ype: Enclosed be	uilding	Property	Use: 419 - 1	or 2 far	nily dwell	ing		
Automatic	Extinguishment Sy	stem Pres	sent: 🗆	Detectors Pre	sent:	Cause of 1	Ignitio	n:	
Aid Given o	or Received: Auto	matic ai	d receiv	red Primary a	ction take	en: 11 - E	xting	uishment by fire service per	rsonnel
Additional a	actions:	12 - S	alvage 8	& overhaul ,	81 - Inci	dent com	mand	1	
Losses		Pre-Inc	cident V	alues					
Property:	\$45,000.00	Property	/: \$12	5,000.00	Civilian	Injuries:	0	Fire Service Injuries:	0
Contents:	\$10,000.00	Content	s: \$20	,000.00	Civilian	Fatalities:	0	Fire Service Fatalities:	0
Total:	\$55,000.00	Total:	\$14	5,000.00	Total Ca	sualties:	0	Total Fire Service Casualties:	0
Total # of a	apparatus on call:			4	Total #	of personne	el on d	all:	10

Special Studies	
COVID 19 was a factor in this incident.	No, COVID 19 was not a factor.

Neighboring Agencies

Agency Name: Broadview Heights Fire Department

Agency ID: 18-017 Agency Type: Fire

Agency Name: Cuyahoga Heights Fire Department

Agency ID: 18-031 Agency Type: Fire

Agency Name: Maple Heights Fire Department **Agency ID:** 18-055

Agency Type: Fire Agency Name: Newburgh Hts **Agency ID:** 18-065

Agency Type: Fire Agency Name: Valley View Fire Department

Agency ID: 18-093 Agency Type: Fire

NARRATIVE (1)

Narrative Title: n/a

Narrative Author: Warner , Joseph Narrative Date: 06/15/2022 08:20:36 Narrative Apparatus ID: n/a

Crews arrived on scene and began extinguishing fire to north exterior wall facing the original fire. Fire was knocked down within three minutes. Crews were then sent inside the home to check for extension and found that fire had traveled almost the whole length of the attic vent. Crews then overhauled and made sure that there was no more extension and fire extinquished.

Utilities were shut off and secured.

Occupants were then directed to find another place to stay for the night.

Unit	F1	Unit	F2
Type:	Ground fire suppression, other	Type:	Ground fire suppression, other
Use:	Suppression	Use:	Suppression
Response Mode:	Lights and Sirens	Response Mode:	Lights and Sirens
# of People	5	# of People	2
Alarm	06 /11/2022 18:39:16	Alarm	06 /11/2022 18:39:16
Dispatched	06 /11/2022 18:39:33	Dispatched	06 /11/2022 18:39:34
Enroute	06 /11/2022 18:40:25	Enroute	06 /11/2022 18:42:01
Arrived	06 /11/2022 18:44:33	Arrived	06 /11/2022 18:45:32
Cancelled	/ / : :	Cancelled	/ / : :
Cleared Scene	06 /12/2022 01:20:06	Cleared Scene	06 /11/2022 22:43:44
In Quarters	06 /12/2022 01:24:40	In Quarters	/ / : :
In Service	06 /12/2022 01:20:06	In Service	06 /11/2022 22:43:44
Unit	SQ 2	Unit	C2 21
Type:	ALS unit	Type:	Chief officer car
Use:	EMS	Use:	Other
Response Mode:	Lights and Sirens	Response Mode:	Lights and Sirens
# of People	2	# of People	1
Alarm	06 /11/2022 18:39:16	Alarm	06 /11/2022 18:39:16
Dispatched	06 /11/2022 18:39:37	Dispatched	06 /11/2022 19:43:10
Enroute	06 /11/2022 18:40:28	Enroute	06 /11/2022 19:43:12
Arrived	06 /11/2022 18:45:35	Arrived	06 /11/2022 20:17:22
Cancelled	/ / : :	Cancelled	/ / : :
Cleared Scene	06 /12/2022 01:23:18	Cleared Scene	06 /12/2022 01:20:06
In Quarters	/ / : :	In Quarters	/ / : :
In Service	06 /12/2022 02:44:15	In Service	06 /12/2022 01:20:06

FIRE			
Acres Burned	None or Less Than One	Acres Burn From Wildland Form	False
Area Of Fire Origin	Wall surface: exterior	Heat Source	Radiated heat from another fire
Item First Ignited	Exterior sidewall covering, surface, finish	Fire Is Confined To Object Of Origin	
Type Of Material	Multiple types of material	Cause Of Ignition	
Factor Contributing To Ignition	Exposure fire		

STRUCTURE FIRE			
Structure Type	Enclosed building	Building Status	In normal use
# Of Stories At Above Grade	1	# Of Stories Below Grade	1
Square Feet	1215	Length	
Width		Floor Of Origin	1
Fire Spread	Confined to building of ori	gin	
Minor Damage	2	Significant Damage	0
Heavy Damage	0	Extreme Damage	0
Item Contributing Most To Spread	Exterior sidewall covering, surface, finish	Type Of Material Contributing Most To Spread	Fiberboard, particleboard, and hardboard
Presence Of Detectors	Present	Type Of Detection System	Smoke
Detector Power Supply	Battery only	Detector Operation	Undetermined

CUSTOM FIELDS FORM	
Is this an accidentally created CAD entry? If it is, then please use incident Code 900 and actions will be action taken other	no
Did a fire Apparatus go as a first responder?	No
Did a fire apparatus go as an assist? Meaning did the engine or ladder go because the call came in as something requiring manpower	no
Was a fire apparatus called to assist for heavy patient or difficult extrication from the home?	no
Did you distribute a smoke detector?	
Did you distribute a battery or batteries?	

PERSONNEL ON CALL			
Name	Personnel Rank	Role(s)	Apparatus
Aldridge, Nicholas	Firefighter 3rd class		SQ 2
Cost , David A	Lieutenant		E1
Havel, Jonathan E	Firefighter 1st class		E1
Kappel , Bryan	Lieutenant		E2
Large, Ronald A.	Firefighter 1st class		E1
McConville , Michael A	Firefighter 1st class		E2
McNeilly, Shane	Firefighter 1st class		SQ 2
Stepka , Melissa L	Firefighter 1st class		E1
Straka , Kevin	Firefighter 1st class		E1
Warner , Joseph M	Executive Captain / Training		C2 21